Cheef ®
safety precautions:
Highly flammable Imitating to eyes.
Irritating to eyes.
Repeated exposure may cause skin dryness or cracking.
Vapours may cause drowsiness and dizziness.
Keep container in a well-ventilated place.
Keep away from sources of ignition - No smoking.
Avoid contact with eyes.
In case of contact with eyes, rinse immediately with plenty of water and seek medical advice
Use suitable gloves.
Use only in well-ventilated areas.
The solvent and its container must be disposed of as hazardous waste.

Cheef®
safety precautions:
Highly flammable Irritating to eyes.
Irritating to eyes.
Repeated exposure may cause skin dryness or cracking.
Vapours may cause drowsiness and dizziness.
Keep container in a well-ventilated place.
Keep away from sources of ignition - No smoking.
Avoid contact with eyes.
In case of contact with eyes, rinse immediately with plenty of water and seek medical advice
Wear suitable gloves.
Use only in well-ventilated areas.
This material and its container must be disposed of as hazardous waste.

CHEEF
Supplier Assessment
SGS
CE

Cheef®
Safety precautions:
Highly flammable Irritating to eyes.
Irritating to eyes.
Repeated exposure may cause skin dryness or cracking.
Vapours may cause drowsiness and dizziness.
Keep container in a well-ventilated place.
Keep away from sources of ignition - No smoking.
Avoid contace with eyes.
In case of contact with eyes. rinse immediately with plenty of
of water and seek medical advice
Wear suitable gloves.
Use only in well-ventilated areas.
This material and its container must be disposed of as
hazardous waste.

CHEEF
Cheef ®
safety precautions:
Highly flammable Imitating to eyes.
Irritating to eyes.
Repeated exposure may cause skin dryness or cracking.
Vapours may cause drowsiness and dizziness.
Keep container in a well-ventilated place.
Keep away from sources of ignition - No smoking.
Avoid contact with eyes.
In case of contact with eyes, rinse immediately with plenty of water and seek medical advice
Wear suitable gloves.
Use only in well-ventilated areas.
This material and its container must be disposed of as hazardous waste.
SGS
CE